




SNORKEL S1 PUMP MOTOR WIRING DIAGRAM

208V/3PH 400Hz
POWER SUPPLY



DUTY CYCLE = 2 MINUTES ON WITH 5 MINUTES OFF

CAUTION

Motor must be phased to ensure proper rotation

3 Phase pumps are capable of running in both forward and reverse, so the pump can pump water in both directions.

MOTOR
7.5HP
208V/3PH
3800 RPM
400 Hz

**** ENSURE PROPER ROTATION ****

If rotation is in the wrong direction, swap any 2 of the Red, Black, or Yellow/White Wires to reverse direction.

MAX AMPS
32.7